

## Aircraft Wire System Test-Bed Defects Fabrication

### DT-1: Insulation Abrasion

**Tools:** Dremel, Drill Bit, Measurement Calibers, Safety Glasses

**Specification:** Location; Percent of Insulation Removed; Linear and Angular Extent;

The following procedure will describe the methods and tools used to fabricate abrasions into the wire used in the Test-Bed. Abrasions will be made with a custom-milling fixture shown in Figure DT1-1 (Dremel Moto-Tool Model # 380-6, Variable Speed).




Figure DT1 –1, Dremel Tool Mounted in Custom Mill.

In an effort to achieve reproducibility the same router bit shall be used in all abrasions put into the Test-Bed wiring. Dremel part number 9903, tungsten carbide bit, shown in Figure DT1-2. The Dremel Tool # 380-6 shall be operated at 28,000 RPM for all work. Because of varying dimensions in the insulations of different wire types used in the Test-Bed, there will be differing amounts of feed used on each wire clamped in the mill. Figure DT1-2 shows two views of a wire clamped in the Dremel Mill.




Figure DT1-2, Showing Two Views of a Wire Clamped in Abrasion Test Fixture.

After wire is clamped into the vise on the mill, the carbide cutter must then be located to within a few mils of the wire insulation. The technique of using a piece of paper (approximately 2 mils thick) between the bit and the insulation will be used. With one hand cranking the X- axis dial and the other hand sliding a small piece of paper between the bit and insulation, move the vise until the paper is just able to be removed from between the bit and wire without tearing (tool is not energized at this time). This technique is shown in Figure DT1-3.




Figure DT1-3, Wire-to-Bit Spacing Adjustment using small Piece of Paper.

Before energizing the tool, make sure the Y-axis feed dial is fully counter clockwise and travel is completed by the stop. Because of the rotation of the tool, all feeds for the lateral abrasions shall be done with one pass. Energize the Dremel and crank in on the X-axis dial to the desired depth. Each cut will be specific to the type of wire and type of cut required. The X-axis dial is marked with .0005" increments. Adjust the Y-axis stop to the specified abrasion length. Crank the Y-axis dial clockwise until the stop is encountered. Turn off Dremel tool and remove wire from vise. Two examples of wire abrasions are shown in Figures DT1-4 and -5.




Figure DT1-4 Partial Wire Insulation Abrasion.




Figure DT1-5, Full Wire Insulation Abrasion Exposing Conductor.

## **DT-2: Insulation Breach**

**Tools:** Stanley 10-099 knife, Stanley 11-921 blade, 25 blade feeler gauge, and calipers set, Fixture #1, Allen Screw Driver, Safety Glasses

**Specification:** Location; Percent of Insulation Removed; Linear and Angular Extent;



Figure DT2-1, Stanley Knife and Blade.



Figure DT2-2, Feeler Gauge Set.

The following procedure will describe the methods and tools used to fabricate three different incisions into the wire used in the Test-Bed. The three different incisions will be referred to as: the straight cut, the lateral breach, and partial insulation removal.

### **The Straight Cut and Lateral Breach**

Measure the overall wire insulation diameter, and the conductor diameter. Subtract the conductor diameter from the insulation diameter. Divide this difference by two, resulting in the insulation thickness on one side of the conductor. Stack the proper amount of feeler gauges on a flat surface to equal the conductor diameter and one side (radius) of insulation thickness. Figure DT2-3 illustrates this Geometry. Figure DT2-4 shows the cutting fixture and feeler gauges.




Figure DT2-3, Drawing of Breach Defect Cutting Geometry.



Figure DT2-4, Breach Defect Cutting Fixture and Feeler-Gauges.

Secure feeler gauges to work surface and lay test wire parallel to the edge of the gauges. Using the Stanley knife press down on the wire insulation until the blade comes in contact with the top surface of the feeler gauge stack and not going below the top surface of gauges. Figures DT2-5 and DT2-6 show the wire in positioned in the cutting fixture and the resulting straight cut.



Figure DT2-5, Wire Positioned in Cutting Fixture.



Figure DT2-6, Straight Cut Result.

Repeat the above-mentioned steps when installing a Lateral Breach, except the razor knife will be laid down to remove the specified length of insulation running along the conductor. Figure DT2-7 shows the wire positioned in the fixture and Figure DT2-8 shows the resulting cut.



Figure DT2-7, Wire Positioned in Fixture Ready for Lateral Cut.




Figure DT2-8, Lateral Cut Result.

Partial Insulation removal process is the same as the straight and lateral cut except the feeler gauge stack needs to be adjusted. The stack used for the lateral cut lined up the knife blade with the conductor, removing all insulation up to the conductor. By adding the proper amount of height to the gauge stack the blade will now remove the desired amount of insulation. Figure DT2-9 illustrates this geometry, and Figure DT2-10 shows a partial cut result.




Figure DT2-9, Drawing of Partial Cut Geometry.



Figure DT2-10, Parital Insulation Removal.

### **DT-3: Cracked Insulation**

**Tools:**

**Specification:** Linear Extent;

The following procedure will describe a method used to fabricate cracked insulation on wires placed in the test bed. The method introduces a specified number of cracks per inch of wire (density) using the straight knife cut procedure described above in DT-2: Insulation Breach. Determine the proper height of feeler gauge stack by using the measuring steps described in DT2. For cuts that do not go all of the way to the conductor, calculate the additional amount of feeler gauge height by multiplying the percent of remaining insulation desired by the insulation thickness. Figure DT2-1 shows the setup for producing a single cut into the insulation. Figure DT3-1 shows the resulting defect after using this procedure.



DT3-1, Resulting Simulated Cracked Insulation Defect from Straight Knife Cuts.

### **DT-4: Conductor Strand Breaks**

**Tools:** Stanley 10-099 knife, Stanley 11-921 blade, 25 blade feeler gauge and calipers set, Fixture #1, Allen Screw Driver, Safety Glasses

**Specification:** Location; Percent of Insulation Removed; Linear and Angular Extent;

The following procedure will describe the method used to fabricate wire conductor partial breakage. Using the procedure described for mounting the wire into the cutting fixture, described in section DT-2, secure the specimen wire and feeler gauges on the cutting fixture. Using the Stanley knife, cut into insulation until side of blade is flush with feeler gauges. Make the cut sufficient to expose conductor strands. Remove the wire from the fixture and using the knife select the particular strand. Using small knife, sever the strand. Repeat the procedure until the specified number of strands is severed. After cutting the individual strands, bend each strand backwards ( $180^{\circ}$ ) so no contact is made with other strand cuts. Tape over defect to hold strands in place and to isolate defect to cut strands only. Figure DT4 – 1 shows the wire mounted in the fixture and strand selection and Figure DT4-2 shows the strand bend fold back




Figure DT4-1, Two Steps Required for a Partial Conductor Strand Cut.




Figure DT4-2, Result of Conductor Strand Cut and Fold-Back.

#### **DT-5: Over-Pressured Clamps**

**Tools:** Harness Clamp and Nut and Bolt, Socket and Torque Wrench, Ratchet, Safety Glasses

**Specification:** Location; Clamp Size, Torque Value

The following procedure will describe the two methods used to over-pressure harness clamps. Figure DT5-1 shows the tools that are needed to produce an over-pressured clamp. Using a clamp that is under sized, remove any padding from the clamp and secure the clamp around the harness at the specified location. The location may correspond to a ribbed structure element of the simulated aircraft fuselage segment location within the enclosure. Using the socket wrench and an appropriately sized ratchet, compress the

clamp around harness to a normal (~10inch-lbs) degree of tightness. Next use the torque wrench to the specified value of clamp tightness or compression (units of ft-lbs). Another variation of this defect type is to allow 1 to 3 wires to be pinched by hardware section of clamp. Both of these over-pressured clamp defects are shown in Figure DT5-2.



DT5-1, Tools Needed for DT5



Figure DT5-2, Two types of over-pressured clamp defects.

Another clamp related defect is due to worn-away clamp plastic insulation, and the action (vibration) of the exposed metallic portion of the clamp rubbing against one or more of the wire insulation. This clamp related defect type can be fabricated by using the procedure described in DT-1 to chaff-off insulation from one or more wires, and a clamp without an insulation barrier is placed over the chaffed wire(s). However, this defect type is similar electrically to a short, or partial short, for a particular wire and is addressed in defect type DT-10 (short wire defect).

### **DT-6: Bend Radius**

**Tools:** Plastic Tie-Bands, Tie-Band Tool

**Specification:** Location; Bend Diameter;

The following procedure will describe the method used to introduce excessive bending radius of harnesses. Ensure that the specimen harness has sufficient length so that when installed into the test bed the connectors are capable of spanning the enclosure length. Bend the harness to the specified harness-to-harness separation in terms of harness diameter. Apply tie-band. Repeat the process to orient the harness on the intended path within the enclosure. Figure DT6-1 shows a zero bend radius defect with two tie bands securing the bends in place and a wire with harness diameter separation metric.




Figure DT6-1, Illustration of Harness Diameter Separation and Applied Tie-Band.

### **DT-7: Faulty Splice**

**Tools:** Butt Splice Joint, Crimp Tool, Heat Shrink Tubing, Heat Gun, Electrical Tape

**Specification:** Location; Severity Type Details (see method description below);

The following procedure will describe three methods used to introduce faulted wire splices. The first method is to cut a specimen wire, remove a half-inch of insulation on each end, and twist the two ends together. The splice is then completed after wrapping electrical tape over the defect. This is shown in Figure DT7-1. The second method inserts each end of the wire to be joined into a butt joint but *with no* crimping and *with* heat applied to heat-shrink tubing that is placed about. This defect is shown in Figure DT7-2 right picture. The last method also uses the butt joint and is crimped *without the use of*

heat shrink tubing or any electrically insulating tape or other material. This defect is shown in the left picture Figure DT7-2.



DT7-1, Example of Faulted Splice



DT7-2, Faulted Splice with no Heat Shrink Tubing, Faulted Splice with no Crimp with Heat Shrink Tubing

### **DT-8: Charred Insulation**


**Tools:** Heat Gun Wire-Mounting Fixture, Adjustable Wrench, Allen Driver, Thermocouple, Digital Thermometer, Safety Glasses, Thermal Protection Gloves

**Specification:** Location; Linear Extent; Exposure Duration;

The following procedure will describe the method used to introduce charred wire specimens. Adjust the height of the heat gun wire-mounting fixture so that the wire holder is approximately 1-inch above the heat gun nozzle. The fixture is shown below in the Figure DT8-1. Turn on the heat gun until the thermometer indicates 500<sup>0</sup>F. Turn off the heat gun and quickly place wire specimen on fixture. Turn on heat gun and expose wire for specified duration. Record exposure time and indicated temperature. Note: Don not allow heat gun to cool down until all desired wires are burned. Figure DT8-2 shows the resulting defects of varying burn severities.



Figure DT8-1, Heat Gun and Wire Mounting Fixture with Close-up View of Wire Positioned Over Heat Gun Nozzle.



DT8-2, Resulting Severities of Burnt Wires

### **DT-9: Opened Conductor**

**Tools:** Wire Cutter, Solder Station, Safety Glasses;

**Specification:** Location; With Contact; Without Contact;

The following procedure will describe the method used to introduce unintended open circuited conditions in wire specimens. Select assembled wire harness and location of where the open circuit defect is to be placed. Select particular wire that is to be electrically opened and use cutters to sever the wire. If no contact is specified cut off ¼-

inch segment of the wire and cover with electrical tape. If contact is to be maintained between each side of the previously un-cut wire, solder together the desired number of strands that correspond to the percentage of contact to be maintained, and cover with electrical tape. For example, solder together half of the strands of each end of wire for fifty percent contact. Figure DT9-1 shows the tools needed to do the procedure. Figure DT9-2 shows the soldering together of wire strands and the resulting defects.



Figure DT9-1, Tools Needed: Wire Strippers, Black Electrical Tape, and Soldering Station.




Figure DT9-2, Soldering of Two Ends of Wire Together to Varying Degrees of Contact.

### **DT-10: Shorted Conductor**

**Tools:** Wire Cutter, O-Lug, Crimper, Solder Kit, Safety Glasses, Sheet Metal Screw, Power Screw Driver, Safety Glasses, Resistors.

**Specification:** Location; Short Path (Differential or Common Mode);

The following procedure will describe two methods used to introduce unintended short-circuited conditions in wire specimens. Select wire specimen and short location. The first method is a wire shorted to the enclosure frame (common mode). Cut wire and crimp on O-lug. Use a sheet metal screw and power drive to attach lug to enclosure frame. The second method will use the lateral breach procedure provided in section DT-2 to remove a segment of insulation of two adjacent wires and then a solder joint to short the two wires together. Figure DT10-1 shows both wire short types. The severity of both types of shorts can be varied by soldering resistors of varying sizes between the ends of the short. This is shown in Figure DT10-2.



DT10-1, Procedure of Soldering Two Wires Together and Screwing O-lug to the Frame



DT10-2, Resistor used to simulate a partial short.